


## Installation Instructions

For installation of KTSE-3 on RXT Transfer Switches



### Installing KTSE-3

Remove connector P-13 and remove RXT control board. Insert connector P-13 plug into KTSE-3 Expander Module and attached to side panel of enclosure. Note: The RXT control board is **not** required to operate the transfer switch in the SLAVE mode and can be removed from the transfer switch.

### Connecting to MASTER TRANSFER switch

**Connect MASTER transfer switch in the normal manner as documented in manufacturers installation manual** (normal connections not shown on this diagram). Connect +12 and -12 volts DC from Master transfer switch control board and connect to KTSE-3 +12 and -12 terminals as marked. Connect the two TRANSFER terminals on KTSE-3 to the LOWER OUTSIDE AUXILIARY switch to the COMMON and **NORMALLY OPEN** terminal connections. **IMPORTANT:** DO NOT use any limit switch's that are not clearly identified as **AUXILIARY CONTACT SWITCHES**. Contact PSP Technical Support should you encounter ANY circumstances other than those shown in the installation instructions.



Important: Risk of electrical shock. This device should only be installed by qualified personnel.